





HYPERMOTARD

C = POWER



invertire questi 2 cavi
reverse these 2 cables



invertire questi 2 cavi
reverse these 2 cables

IT

Attenzione: Per Hypermotard (tutti i modelli),
invertire la polarità 0V <-> 12V sul
connettore C come in figura

FR

Attention: Sur Hypermotard (tous les modèles),
inverser la polarité 0V <-> 12V sur le
connecteur C selon le schéma ci-joint.

ENG

Warning: On Hypermotard (all models),
reverse the polarity 0V <-> 12V
on connector C as attached drawing